Approved For Release 2003/01/24 : CIA-RDP67B00511R000100110016-2

COUPLER RETROFIT STATUS

4/17/64

L. Cou	oler	Oven	TCA
--------	------	------	-----

- e. Design from field complete
- b. Perts on hand for 5 Kits
- c. Kit build on 5 25% complete

2. 7.2KC Filter Board (Noise Problem)

- a. Design from field complete
- b. All parts on hand
- c. Twenty Kits 10% complete.

3. Level Discriminator (Noise Problem)

- a. Design from Mela complete
- b. All parts on hand
- c. Twenty Kits available 4/26/64
- 4. 400 CPS Demodulator Driver Add Socoupling (Change from couper wave to detail
 - a. Design from field complete
 - b. Parts 80% on hand
 - c. Assembly 20% complete

5. Resolver Filter Assembly

- a. Design from field complete
- b. Parts 20% complete
- c. Assembly not complete
- 6. Gyro & Accelerometer Gate Boards Replace Gate translators with lower has

٥.	Dosign	and	test	in	Meld	in.	process.

٥.	

C.

7. D. C. Amplifier -

No design - will unit to see if other changes make this necessary.

S. Accolorometer Current Supply

Dosign due into house 15 May.

9. Av Transformer

Waiting to be certain it is necessary.